

Figure E.15 Surface Corrosion at Mid Section for 0.0% Chloride (Set#2)




Figure E.16 Rib Loss at Mid Section for 0.0% Chloride (Set #2)